

Datacom Systems Inc.

December 20, 2016

**9 Adler Dr.**

**East Syracuse, NY 13057**

**Phone: +1-315-463-9541**

**Support: [www.datacomsystems.com](http://www.datacomsystems.com)**

## Release Notes

Supported Models: **DS-1404, DS-1406, TS-1404, TS-1406, TS-2408**

Upgrade File Name: **firmware.tar**

Compatible Terminal Emulators: **Putty, Tera Term**

**APPLICATION VERSION: 111816A1**

## Changes in version 111816A1

### 1. Additions

Initial release for models: SINGLEstream models TS-1404, TS-1406 and TS-2408. Also support models DS-1404 and DS-1406.

## Release Notes:

- Teraterm is the preferred telnet client. Issues have been seen with Microsoft Telnet.
- SFP Reinsertion - If an SFP is removed and reinserted, the lights on the front of the unit will remain lit.
- Non-Graceful SSH Disconnect Results in Being Locked Out – Type “exit” before leaving SSH. When SSH is disconnected in a non-graceful manner, the unit is not able to be logged in on through any authentication method until the CLI timeout is reached, or the unit is power cycled.
- Management Port - 10/100M Capability: On the initial boot, the connection requires a 1G connection on the management port.
- Use ? to display the full list of commands.
- In the current version the firmware has to be named “firmware.tar”
- On the Bypass (DS-XXXX model) versions, the appliance pairs should be the same speed at all times.
- The appliance Network Pair Speeds must match on the Bypass (DS-XXXX model) models.
- The System Set Time command displays two outputs. The first one setting the date, the second setting the time.
- Backspacing through prompt - In these models it is possible to backspace through the prompt. This is a visual effect only, commands are not impacted.