

# **Datacom Systems Inc.**

9 Adler Dr.

East Syracuse, NY 13057 Phone: +1-315-463-9541

Support: www.datacomsystems.com

#### **Release Notes**

Firmware for: All DS-1010 models.

Upgrade File Name: vmlinux.64.gz

Compatible Browsers: Goggle Chrome, Microsoft Internet Explorer, Mozilla Firefox


Release Version: 2894

### **Objective:**

The objective of this document is to provide additional information about the changes for the Durastream product line when upgrading to the 2894 release.

### **Image Upgrade:**

The new image can be upgraded on the Durastream through HTTP.





## **Release Notes**

Users need to browse for the firmware and click Upload Firmware. Most importantly, the file must be gunzipped; the naming can vary.

The upgrade procedure will take 3-5 minutes. It is important that the user does not disturb the unit at this time. Once completed, the unit will automatically reboot with the newest image.

### **Resolved Issues:**

1. CLI and GUI no longer hangs when Email Notification is enabled and Heartbeat Timer set between 200-300ms.

#### **Known Issues:**

2. Test Email works though error pops up in GUI